

Fuel Filters .....	47
Fuel Line .....	46
Impellers .....	48
Lower Unit Seal Kits .....	48
Oil Filters .....	47
Sleeves .....	45
Sparkplugs .....	45
Water Separators .....	47



New York • 1-800-222-3375  
631-244-8060 • fax 631-244-0556  
61 Floyd Run, Bohemia, NY 11716



Puerto Rico  
787-832-2499 • fax 787-832-2939  
234 Balboa St., Mayaguez, Puerto Rico 00681-2605  
e-mail: [info@wsmparts.com](mailto:info@wsmparts.com) • [www.wsmparts.com](http://www.wsmparts.com)





Code:  
CL= Cast in Sleeve Liner



Model	Year	Cyl.	Bore Size	Sleeve Description	O.D.	Sleeve Length	Type	Brand	Part No.
BF-9.9 / BF-15		2	2.283"	Straight sleeve, no ports	2.535"	3.560"	CL	La Sleeve	L1630B
BF-75 / BF-100		2	2.204"	Straight sleeve, no ports			CL	La Sleeve	FL0310B
50 HP	2000	3	2.748"	Straight 4 Stroke Sleeve	3.000"	4.625"		Advanced	1158SA
50 HP	2000	3	2.748"	Straight 4 Stroke Sleeve	3.020"	4.625"		Advanced	1158SB
115 HP	1996-2006	4	3.386"	Straight 4 Stroke Sleeve	3.510"	6.000"		Advanced	1157SA
115HP	1996-2006		3.386"	Straight 4 Stroke Sleeve	3.530"	6.000"		Advanced	1157SB
225 HP		6	3.500"	Straight 4 Stroke Sleeve	3.660"	5.225"		Advanced	1196SA
225 HP		6	3.500"	Straight 4 Stroke Sleeve	3.680"	5.225"		Advanced	1196SB

## Honda Spark Plugs



Part No.
BPR5ES
CR5EH-9
DR5HS
DR6HS
DR7EA
IZFR6F11
ZFR7F



New York • 1-800-222-3375  
631-244-8060 • fax 631-244-0556  
61 Floyd Run, Bohemia, NY 11716



Puerto Rico  
787-832-2499 • fax 787-832-2939  
234 Balboa St., Mayaguez, Puerto Rico 00681-2605  
e-mail: info@wsmparts.com • www.wsmparts.com



## Honda Fuel



**9" Silverado Fuel Line assembly**  
Part No. 18-81042EP

O.E. No. 17700-ZW9-010,  
17700-ZW9-020  
Complete 9" fuel line assembly with  
3/8" fuel line Fits 8, 9.9, 15, 25, 30, 40,  
50, 75, 90, 115, 130 HP (2001-2002)



**Fuel Connector**  
Part No. 18-80400

O.E. No. 16977-ZV5-A00  
Male tank outlet, new style, 1/4" NPT  
Mates with 18-80401




**Fuel Connector**  
Part No. 18-80401

Female hose connector, New style,  
3/8" hose WILL NOT interchange with  
OE 5/16" hose assemblies.  
Mates with 18-80400.



**Fuel Connector**  
Part No. 18-80403

Female Hose connector with  
rectangular locking post, Will not  
interchange w/ OE's 5/16" hose  
assmbles. For late model engine.  
For use with 18-81042 Fuel hose  
assmbles



**Fuel Connector**  
Part No. 18-80406

O.E. No. 16977-ZV5-900  
Male tank outlet, old style, 1/4" NPT



**Fuel Connector**  
Part No. 18-80408

O.E. No. 17650-ZW9-003  
Female 5/16" connector with  
rectangular Locking post.  
Fits late model engines



**Fuel Connector**  
Part No. 18-80420

O.E. No. 17650-921-003ZB  
1/4" version of 18-80408.  
Mates with 17710-881-00ZA



**Fuel Connector**  
Part No. 18-80407

O.E. No. 17710-ZW9-033  
5/16" with interlocking post. Fits; BF8-  
130 (2003)



**COMPLETE FUEL FILTER**

Part No. \_\_\_\_\_  
**18-7720**

Replaces: 16900-SR3-004  
 For BF115,BF130,AX, AY, A1  
 Series#14ZW50E1M



**COMPLETE FUEL FILTER**

Part No. \_\_\_\_\_  
**18-7786**

Replaces: 16900-SR5-004  
 For BF35/45AM, BF4050A, AW, AX  
 Series #14ZV50M:BF75,BF90,AT,  
 AW,AX, AY  
 Series#14ZW00E1M



**COMPLETE FUEL FILTER**

Part No. \_\_\_\_\_  
**18-7785**

Replaces: 16010-ST5-993  
 For:BF115,BF130,AX,AY,A1  
 Series#14ZW50E1M

## Honda Water Separators



**Water Fuel Separator with Bracket**

Part No. **600-402**

Fits: Mercury, Yamaha,  
 Honda, Suzuki Merc Cruiser  
 Standard Canister, 1/4" npt



**Water Fuel Separator with Bracket**

Part No. **600-404**

Fits: Mercury, Yamaha,  
 Honda, Suzuki Merc Cruiser  
 Standard Canister, 3/8" npt

## Honda Oil Filters



**OIL FILTER**

Part No. \_\_\_\_\_  
**18-7910**

Replaces 15400-POH-30, 15400-POH-305PI  
 75 HP & UP, BF75, BF90, AT, AW, AX, AY  
 Series # 14ZW00E1M, BF115,BF130,AX,  
 AY, A1  
 Series# 14ZW50E1M



**OIL FILTER**

Part No. \_\_\_\_\_  
**18-7911**

Replaces 15400-PFB-004  
 For: BF25, BF30, A, AW, AX, AY,  
 Series# 14ZV90E1M, BF34/45AM  
 BF40/50A, AW, AX, Series  
 14ZV50M



New York • 1-800-222-3375  
 631-244-8060 • fax 631-244-0556  
 61 Floyd Run, Bohemia, NY 11716




Puerto Rico  
 787-832-2499 • fax 787-832-2939  
 234 Balboa St., Mayaguez, Puerto Rico 00681-2605



e-mail: [info@wsmparts.com](mailto:info@wsmparts.com) • [www.wsmparts.com](http://www.wsmparts.com)

# Honda Impellers




HP	OEM	Year	Impeller	OEM	Service Kit
BF5	19210-881-A01, -A02		700-160	06192-ZV1-C00	18-3278
BF7.5	19210-881-A01, -A02		700-160		
BF8	19210-881-A01, -A02		700-160	06192-881-C00	18-3279
BF8	19210-ZV4-651		700-170		
BF8D/9.9D	19210-ZW9-013, 003		18-3100		
BF9.9	19210-ZV4-013	AH,AK,AM,AW	700-165	06192-ZV4-000	18-3280
BF9.9	19210-ZV4-651	AX, AY,	700-170		
BF10	19210-881-A01, -A02		700-160		
BF15	19210-ZV4-013	AH,AK,AM,AW	700-165		
BF15	19210-ZV4-651	AX, AY, A1,A2	700-170	06192-ZV4-000	18-3280
BF20	19210-ZV7-003		700-180		
BF25/30	19210-ZV7-003		700-180	06192-ZV7-000	18-3281
BF35/40/45/50	19210-ZV5-003	(97 & UP)	700-175	06192-ZV5-003	18-3282
BF75/90	19210-ZW1-B04	AX & LATER	700-185	06192-ZW1-000	18-3283
BF75/90	19210-ZW1-303	('96-98)	700-155	19021-ZW1-003	725-155
BF75/BF100	19210-881-A01, -A02	(PRE 1997)	700-160		
BF90/115/130	19210-ZW1-B04	(03 & UP)	700-185	06192-ZW1-000	18-3283
BF135-225	19210-ZY3-003	('02 & UP)	700-150		
BF200/225	19210-ZY3-003	(02 & UP)	700-150	06192-ZY3-000	18-3285

## Honda Lower Unit Seal Kits




BF 9.9/BF 15  
Part No. 18-8363



BF 20  
Part No. 18-8364



BF 35/45 AM BF 40/50 A/AW/AX  
Part No. 18-8362-1



BF 75 BF 90  
Part No. 18-8366



BF 115/ BF 130  
Part No. 18-8365



Arizona • 1-800-977-1414  
480-966-1550 • fax 480-966-1565  
16441 N. 91St. Suite 105 Scottsdale, AZ 85260  
e-mail: info@wsmparts.com • www.wsmparts.com



Florida • 1-866-417-4072  
941-238-0960 • fax 941-238-0965  
6225 21St. E, Suite B, Bradenton, FL 34203

