

Boyesen Reeds-----	346
Carburetor Kits-----	346
CDI Electronics-----	348
Gasket Kits-----	345
Impellers-----	347
Pistons, Wiseco-----	343-344
Sleeves, Cylinder-----	345
Tilt Tube Grease Nuts-----	347




New York • 1-800-222-3375
631-244-8060 • fax 631-244-0556
61 Floyd Run, Bohemia, NY 11716



Puerto Rico
787-832-2499 • fax 787-832-2939
234 Balboa St., Mayaguez, Puerto Rico 00681-2605
e-mail: info@wsmparts.com • www.wsmparts.com





MODEL	Cyl.	Bore	Piston No.	Ring No.
Tohatsu/Nissan 25HP	2	2.677"/Std.	3157PS	2678KD
Loop Charge		2.697"/.020	3157P2	2697KD
M25C2		2.707"/.030	3157P3	2707KD
		2.717"/.040	3157P4	2717KD
		Wrist Pin	S540	
		Circlip	CW17	
Tohatsu/Nissan 30HP	2	2.677"/Std.	3157PS	2678KD
Loop Charge		2.697"/.020	3157P2	2697KD
M30A3		2.707"/.030	3157P3	2707KD
		2.717"/.040	3157P4	2717KD
		S540		
		CW17		
Tohatsu/Nissan 40HP	2	2.755"/Std.	3155PS	2755KD
Loop Charge		2.775"/.020	3155P2	2775KD
M40C		2.785"/.030	3155P3	2785KD
		2.795"/.040	3155P4	2795KD
		Wrist Pin	S523	
		Circlip	CW17	
Tohatsu/Nissan 40HP	3	2.677"/Std.	3156PS	2678KD
Loop Charge		2.697"/.020	3156P2	2697KD
M40D		2.707"/.030	3156P3	2707KD
		2.717"/.040	3156P4	2717KD
		Wrist Pin	S540	
		Circlip	CW17	
Tohatsu/Nissan 50HP	3	2.677"/Std.	3156PS	2678KD
Loop Charge		2.697"/.020	3156P2	2697KD
M50D		2.707"/.030	3156P3	2707KD
		2.717"/.040	3156P4	2717KD
		Wrist Pin	S540	
		Circlip	CW17	
Tohatsu/Nissan 60HP	2	3.385"/Std.	3153PS	3385KD
Loop Charge		3.405"/.020	3153P2	3405KD
M60A		3.415"/.030	3153P3	3415KD
		3.425"/.040	3153P4	3425KD
		Wrist Pin	S544	
		Circlip	CW20	
Tohatsu/Nissan 60HP	3	2.913"/Std.	3154PS	2913KD
Loop Charge		2.933"/.020	3154P2	2933KD
M60B		2.943"/.030	3154P3	2943KD
		2.953"/.040	3154P4	2953KD
		Wrist Pin	S512	
		Circlip	CW20	



New York • 1-800-222-3375
631-244-8060 • fax 631-244-0556
61 Floyd Run, Bohemia, NY 11716



Puerto Rico
787-832-2499 • fax 787-832-2939
234 Balboa St., Mayaguez, Puerto Rico 00681-2605
e-mail: info@wsmparts.com • www.wsmparts.com





3154



3155

MODEL	Cyl.	Bore	Piston No.	Ring No.
Tohatsu/Nissan 70HP	2	3.385"/Std.	3153PS	3385KD
Loop Charge		3.405"/.020	3153P2	3405KD
M70A		3.415"/.030	3153P3	3415KD
		3.425"/.040	3153P4	3425KD
		Wrist Pin	S544	
		Circlip	CW20	
Tohatsu/Nissan 70HP	3	2.913"/Std.	3154PS	2913KD
Loop Charge		2.933"/.020	3154P2	2933KD
M70B		2.943"/.030	3154P3	2943KD
		2.953"/.040	3154P4	2953KD
		Wrist Pin	S512	
		Circlip	CW20	
Tohatsu/Nissan 90HP	3	3.385"/Std.	3153PS	3385KD
Loop Charge		3.405"/.020	3153P2	3405KD
M90A		3.415"/.030	3153P3	3415KD
		3.425"/.040	3153P4	3425KD
		Wrist Pin	S544	
		Circlip	CW20	
Tohatsu/Nissan 115HP	4	3.464"/Std.	3152PS	3464KD
Loop Charge		3.484"/.020	3152P2	3484KD
M115A		3.494"/.030	3152P3	3494KD
		3.504"/.040	3152P4	3503KD
		Wrist Pin	S544	
		Circlip	CW20	
Tohatsu/Nissan 120HP	4	3.464"/Std.	3152PS	3464KD
Loop Charge		3.484"/.020	3152P2	3484KD
M120A		3.494"/.030	3152P3	3494KD
		3.504"/.040	3152P4	3503KD
		Wrist Pin	S544	
		Circlip	CW20	
Tohatsu/Nissan 140HP	4	3.464"/Std.	3152PS	3464KD
Loop Charge		3.484"/.020	3152P2	3484KD
M140A		3.494"/.030	3152P3	3494KD
		3.504"/.040	3152P4	3503KD
		Wrist Pin	S544	
		Circlip	CW20	



3156



3157



Arizona • 1-800-977-1414

480-966-1550 • fax 480-966-1565

16441 N. 91St. Suite 105 Scottsdale, AZ 85260

e-mail: info@wsmparts.com • www.wsmparts.com

Florida • 1-866-417-4072

941-238-0960 • fax 941-238-0965

6225 21St. E. Suite B, Bradenton, FL 34203



Code:

- AC= Alloy-Chrome Bore
- RS= Replacement sleeve
- CC= Original Barrel is Cast Iron
- CS= Cast Sleeve
- CL= Cast in Sleeve Liner


*Oversizes Available



Model	Year	Cyl.	Bore Size	Sleeve Description	Thickness	O.D.	Sleeve Length	Type	Brand	Part No.
18 HP	1998	2	2.626"	Straight Sleeve with ports		2.960"		RS	Advanced	1171SA
25 HP	90-00	2	2.677"	Staight Sleeve with ports, length + .020 to allow for decking	1/8"	2.960"	4 7/8"	RS	La Sleeve	L126-OB
30 HP		2	68mm		-				Advanced	1059SA
					-				Advanced	1059SB
40 HP	85-95	2	2.755"	Staight sleeve with ports 70mm		3.017"	5.155"	RS	La Sleeve	L064-OB
					-				Advanced	1058SA
					-				Advanced	1058SB
40 HP	94-00	3	2.677"	Straight Sleeve with ports, length + .015 to allow for decking	1/8"	2.940"	5.115"	RS	La Sleeve	L123-OB
50 HP	92-00	3	68mm		-				Advanced	1057SA
					-				Advanced	1057SB
50 HP	86-91	2	3.189"	Straight sleeve with ports, 81mm	1/8"	3.195"	5.840"	RS	La Sleeve	L065-OB
55 HP	86-91	2	81mm		-				Advanced	1133SA
					-				Advanced	1133SB
60 HP	91-95	3	2.914"	Straight sleeve with ports, length + .020 to allow for decking	1/8"	3.195"	5.840"	RS	La Sleeve	L124-OB
70 HP	94-04	3	74mm		-				Advanced	1056SA
					-				Advanced	1056SB
70 HP	86-90	2	3.385"	Straight sleeve with ports 86mm	1/8"	3.745"	5.905"	RS	La Sleeve	L066-OB
					-				Advanced	1083SA
					-				Advanced	1083SB
90 HP	93-04	3	3.385"	Straight sleeve with ports, 86mm length + .020 to allow for decking				RS	La Sleeve	L122-OB
					-				Advanced	1046SA
					-				Advanced	1046SB
115 HP	95-00	4	3.464"	Straight sleeve with ports, length + .020 to allow for decking	1/8"	3.787"	5.905"	RS	La Sleeve	L138-OB
120 HP	93-04	4	88mm		-				Advanced	1055SA
140 HP	93-04	4			-				Advanced	1055SB


Gasket Kits / Oil Seals

Tohatsu Power Head Gasket Kit - Available as Kits Only




Part No. 500-400

40-50 HP



Part No. 500-405

60-70 HP



Part No. 500-410

90 HP

Application Chart

HP	Cyl.	Gasket Kit
40/50	3	500-400
60/70	3	500-405
90	3	500-410



New York • 1-800-222-3375

631-244-8060 • fax 631-244-0556

61 Floyd Run, Bohemia, NY 11716

e-mail: info@wsmparts.com • www.wsmparts.com




Puerto Rico

787-832-2499 • fax 787-832-2939

234 Balboa St., Mayaguez, Puerto Rico 00681-2605



Nissan / Tohatsu Carburetor Kits



Part No. 18-7290
OE No. 84419M




Part No. 600-50
OE No. 346-87122-0



Part No. 18-7765
OE No. 369-87122-1

Nissan / Tohatsu **Boyesen Reeds**



Model	Year	Part No.
8HP	ALL	T13P
9.9HP (#M9.9B2)	ALL	T13
12HP (#M12C2)	ALL	T13
15HP (#M15B2)	ALL	T13
18HP (#M18C2)	ALL	T13
25HP (#M25C2)	ALL	T22
30HP (#M30A3)	ALL	T22
35HP (#M35C)	ALL	T23
40HP (#M40C)	ALL	T23
40HP (#M40D)	ALL	T32
45HP (#M45A2)	ALL	T23P
50HP (#M50C)	ALL	T23P
50HP (#M50D)	ALL	T32
60HP (#M60A)	ALL	T23P
60HP (#M60B)	ALL	T33P
70HP (#M70A2)	ALL	T23P
70HP (#M70B)	ALL	T33P
90HP (#M90A)	ALL	T33
120HP (#M120A)	ALL	T43
140HP (#M140A)	ALL	T43



HP	Year	Impeller
25	2003	700-360
30	2003	700-360
40	2004	700-360
40	2003	700-355
50		700-355

Lower Unit Grease Nuts



CABLE GREASE NUT

Part No. 986-500

1" x 14 Pitch Thread

Built in Grease seal with easy steer nuts, it lubricates and seals out moisture and salt water. Extends cable life the inexpensive way. Easy installation. Fits Merc, Mariner, OMC, Yamaha, Suzuki Chrysler/Force and Nissan. Anodized. (Fits Most Mercs)



CABLE GREASE NUT

Part No. 986-505

7/8" x 14 Pitch Thread

(Fits All Others)



CABLE NUT FOR CABLE SIDE

Part No. 986-510

7/8" X 14 Pitch Threads I.D. or O.D.

This nut injects oil directly onto cable.
FITS ALL OUTBOARDS



New York • 1-800-222-3375

631-244-8060 • fax 631-244-0556

61 Floyd Run, Bohemia, NY 11716

e-mail: info@wsmparts.com • www.wsmparts.com



Puerto Rico

787-832-2499 • fax 787-832-2939

234 Balboa St., Mayaguez, Puerto Rico 00681-2605



IGNITIONS



119-2400 CD Module 2 Cyl Engine

Replaces: 303062400M 30306-2400
 303-06240-0 353062600M 35306-2600
 353-06260-0 353062602M 353-06260-2
 35306-2602M 362060600M 36206-0600
 362-06060-0 3A3062400M 3A306-2400
 3A3-06240-0



119-2402 CD Module 2 Cyl Engine

Fits: 25 HP S/N 27906-up 30 HP S/N 21031-up with long spark plug leads.

Replaces: 346062602M 34606-2602
 346-06260-2 3A1062402M 3A106-22402
 3A1-06240-2 3A1062601M 3A106-2601
 3A1-06260-1 3A1062602M 3A106-2602
 3A1-06260-2



119-3G2-01 CD Module 2 Cyl Engine

Replaces: 3G2060601M 3G206-0601
 3G2-06062-1

RECTIFIERS/RECTIFIER/REGULATORS



158-9501 Rectifier

Replaces: 353760601M 35376-0601M
 353-76060-1 361760600M 36176-0600M
 361-76060-0 362760600M 36276-0600M
 362-76060-0 3B2760600M 3B276-0600M
 3B2-76060-0